



ARKANSAS
Department of Environmental Quality

September 23, 2014

Honorable Nina Thornton, Mayor
City of Hardy
P.O. Box 5
Hardy, AR 72542

RE: City of Hardy WWTP Sanitary Sewer Overflow Inspection (Sharp Co)
AFIN: 68-00018 NPDES Permit No.: AR0037991

Dear Mayor Thornton:

On September 10, 2014, I performed a Reconnaissance Inspection of the above referenced facility in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. A copy of the inspection report is enclosed for your records.




No violations were noted at the time of the inspection. Please refer to the attached inspection report for any comments.

If I can be of any assistance, please contact me at saunders@adeq.state.ar.us or (870) 424-3322 ext. 3.

Sincerely,

A handwritten signature in black ink, appearing to read "Sean Saunders", is written over a horizontal line.

Sean Saunders
District 10 Field Inspector
Water Division

 A R K A N S A S Department of Environmental Quality		WATER DIVISION INSPECTION REPORT					
		AFIN: 68-00018		PERMIT #: AR0037991		DATE: 9/10/2014	
		COUNTY: 68 Sharp		PDS #: 079855		MEDIA: WN	
		GPS LAT: 36.32581 LONG: -91.476124 LOCATION: General Area					
FACILITY INFORMATION			INSPECTION INFORMATION				
NAME: City of Hardy WWTP LOCATION: Off Burton Street of Woodland Hills Drive CITY: Hardy			FACILITY TYPE: 1 - Municipal	INSPECTOR ID#: 71153 S - State			
			FACILITY EVALUATION RATING: 3 - Satisfactory		INSPECTION TYPE: SSO/Collection System		
			DATE(S): 9/10/2014	ENTRY TIME: 11:30	EXIT TIME: 12:30	PERMIT EFFECTIVE DATE: 1/1/2013	
					PERMIT EXPIRATION DATE: 12/31/2017		
RESPONSIBLE OFFICIAL			INSPECTION PARTICIPANTS				
NAME / TITLE: Honorable Nina Thornton / Mayor COMPANY: City of Hardy MAILING ADDRESS: P.O. Box 5 CITY, STATE, ZIP: Hardy AR 72542 PHONE & EXT. / FAX: 870-856-3811 / EMAIL:							
CONTACTED DURING INSPECTION: Yes							
FAYETTEVILLE SHALE RELATED: N FAYETTEVILLE SHALE VIOLATIONS: N							
AREA EVALUATIONS							
(S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)							
S	PERMIT	N	FLOW MEASUREMENT	N	STORMWATER		
N	RECORDS/REPORTS	N	LABORATORY	S	FACILITY SITE REVIEW		
S	OPERATION & MAINTENANCE	S	EFFLUENT/RECEIVING WATER	N	SELF-MONITORING PROGRAM		
N	SAMPLING	N	SLUDGE HANDLING/DISPOSAL	N	PRETREATMENT		
N	OTHER:						
SUMMARY OF FINDINGS							
No violations were noted at the time of the inspection.							
GENERAL COMMENTS							
On September 10, 2014, I performed a reconnaissance inspection of the grinder pump at 214 Robin Hood Ln in Hardy, AR in response to a complaint. The complainant alleged that City of Hardy employees were pumping raw sewage into a drainage that flowed into Lake Sherwood in the Woodlawn Hills subdivision. At the time of the inspection, there was no evidence of raw sewage being pumped into the drainage.							
INSPECTOR'S SIGNATURE: 			Sean Saunders		DATE: 9/19/2014		
SUPERVISOR'S SIGNATURE: 			Kerri McCabe		DATE: 9/22/2014		

Water Division Photographic Evidence Sheet

Location:	City of Hardy WWTP				
Photographer:	Sean Saunders	Date:	9/10/2014	Time:	11:53
Witness:	None	Photo #:	1		
Description:	Grinder pump with drainage to the lake in the background.				



Photographer:	Sean Saunders	Date:	9/10/2014	Time:	11:58
Witness:	None	Photo #:	2		
Description:	Drainage beside the grinder pump with no evidence of raw sewage.				

